



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Re: TD09F Situation Report No. 3 as at 0800 Hours – Wednesday 8 February 2017

This situation report is to advise of the status of FRA's assets due to the effects of TD09F.

- Queens Road at Waimalika, Nadi is closed to all light vehicles
- Queens Road at Nadi Back Road along Tata's Restaurant to Pacific Energy is closed to all light vehicles
- Kings Road is open
- Some roads in the urban and low-lying areas are still in danger of flooding as rainfall continues in some parts of Fiji.
- Please remain vigilant, tune into the local radio and listen to the advice of emergency services.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

CENTRAL DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	1200 06/2/17	Closed	Monitor water levels	Unknown		
Korovou	Naboro Cocoa Rd	Delekado Crossing	Water receded	1200 06/2/17	Open	Monitor water levels	Unknown	7/2/17 0700	Water receded
Korovou	Nasaibitu Rd	Waisa Crossing	Water receded	1200 06/2/17	Open	Monitor water levels	Unknown	7/2/17 0700	Water receded
Levuka	Ovalau Circular Rd	Rukuruku Crossing	Water receded	1000 06/2/17	Closed to heavy vehicles	Reinstate washout	Unknown	7/2/17 0700	Reinstated by hand with assistance from Villagers



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

WESTERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Rakiraki	Nailuva Road	Burelevu Crossing	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Katudrau Road	Katudrau Crossing	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Waimari Road	Qalau Flat	Flooding	7/2/17=7am	Open to all Traffic			07/02/2017 11am	Water Level Receded
Rakiraki	Narara Road	4 Crossing	Flooding	7/2/17=7am	Open to all Traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Lau Road	Fort Crossing	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nausori Road	Fort Crossing	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Rakiraki	Bainisoqos oqo Road	Crossing	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Barotu Cr Road	Crossing	Flooding	7/2/17=7am	Open to all Traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Burenitu Road	Crossing	Flooding	7/2/17=7am	Open to all Traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Naqoro Flat	Rakiraki Town Approach	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA	07/02/2017 11am	Water Level receded
Rakiraki	Korotale Road	Drana Crossing	Flooding	7/2/17=7am	Open to all Traffic	Awaiting Water Level to Recede	TBA	07/02/2017 11am	Water Level receded. Clear Debris and backfill
Rakiraki	Kings Rd	New Rakiraki Bridge, Nacovi Flat	Flooding	7/2/17=7am	Open to all Traffic	Awaiting Water Level to Recede	TBA	06/02/17 6pm	Water Level Receded
Rakiraki	Nasomo	CH300	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA	07/02/2017 11am	Water Level receded



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Rakiraki	Ganilau Rd	Crossing	Flooding, washout	7/2/17=3pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Vatukoula Ind	CH700	Uneven Surfaces	7/2/17=3pm	Closed to all traffic	Work in progress. Backfill surface with metal	07/02/17 7pm		
Tavua	Yaladro	CH0-Ch4600	Flooding	7/2/17=7am	Open to 4x4 and heavy vehicles only. Drive with Caution	Awaiting Water Level to Recede	TBA		
Tavua	Nabuna Village Rd	CH0-Ch700	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Rukuruku	CH2500-Ch3000	Flooding	7/2/17=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Naseyani	Ch2400	Underwater	8/2/17 - 7.30am	Closed to all traffic		TBA		
Tavua	Mataniwai Rd	CH1300	Underwater	8/2/17 - 7.30am	Closed to all traffic		TBA		
Tavua	Lakalaka	CH800	Flooding	7/2/17=7am	Open to all Traffic			07/02/17 11am	water level receded
Tavua	Dramasi	CH200	Flooding	7/2/17=7am	Open to all Traffic			07/02/17 11am	water level receded



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Tavua	Nadelei	CH1400	Flooding	7/2/17=7am	Open to all Traffic			07/02/17 11am	water level receded
Tavua	Kings Rd	Tavua Bridge Approach	Flooding	7/2/17=7am	Open to all Traffic			07/02/17 11am	water level receded
Tavua	Kings Rd	Tavua Bridge Approach	Flooding	7/2/17=7am	Open to all Traffic			07/02/17 7am	water Level receded
Ba	Navala Road	Navala Crossing	Flooding	06/02/17=3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Ba	Varadoli Cemetry Road	Crossing	Flooding	07.07.2017=7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Ba	Varadoli Road	Crossing	Flooding	07.07.2017=7am	Situation unknown until reports come back from depot			07/05/17 3pm	Water Level receded. Debris were cleared
Ba	Koroboya Road	Crossing	Flooding	07.07.2017=7am	Situation unknown until reports come back from depot			07/05/17 3pm	Water Level receded. Debris were cleared
Ba	Vutuni Road	3rd Crossing	Flooding	07.07.2017=7am	Closed to all traffic	Awaiting Water Level to Recede			
Ba	Marinitawa Road	1st Crossing	Flooding	07.07.2017=7am	Closed to all traffic	Awaiting Water Level to Recede			



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Ba	Toge Road	1st Crossing	Flooding	06/02/17=4.30pm	Closed to all traffic	Awaiting Water Level to Recede			
Ba	Babrihan Road	1st Crossing	Flooding	06/02/17=4.30pm	Closed to all traffic	Mobilise Machines From Koroboya Crossing to Babrihan Crossing once work completed at Koroboya.			
Lautoka	Navula Road	Navula Crossing	Under water	6/2/17=1.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Buabua Road	Buabua Crossing	Under water	6/2/17=1.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Vakabuli Paipai Road		Under water	6/2/17=1.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Drasa Dam Road		Under water	6/2/17=1.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Vaivai Road	Vaivai Crossing	Under water	6/2/17=1.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Saru Back Road	Saru Crossing	Under water	6/2/17=2.00 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Lautoka	Abaca Road		Under water	6/2/17=2.00 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Tomuka Road		Culvert Under water	6/2/17=2.15 pm	Open to all Traffic		07/02/17 3.30pm		Water Level Receded
Lautoka	B.S.Charan		Surface washout & Culvert washout	6/2/17=2.30 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Vuda Back Road		Flooding	6/2/17=2.36 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Tavakubu Road		Flooding	6/2/17=2.45 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Queens Road		Flooding	6/2/17=2.45 pm	Open to all Traffic			07/02/17 3pm	Water Receded
Lautoka	Vakabuli Paipai Road		Under water	6/2/17=2.45 pm	Closed To All Traffic	Awaiting Water Level to Recede	TBA		
Lautoka	Buabua Road	Buabua Flat	Flooding	6/2/17=3.35 pm	Open to all Traffic			07/02/17 3pm	Water level receded
Nadi	Nadi Back Rd	Along Tata'S Resturant to Pacific Energy	Flooding	6/2/17=3.00 pm	Open to 4x4 and heavy vehicles only. Drive with Caution				Water level receded
Nadi	Queens Road	Waimalika	Flooding	8/02/2017 8am	Open to 4x4 and heavy				



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

					vehicles only. Drive with Caution				
Nadi	Solovi Rd	Solovi Rd Crossing 1 & 2	Flooding	7/2/17=7.30 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nadi	Mate Rd	Mate Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nadi	Chunilal Rd	Chunilal Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nadi	Savalau Rd	Savalau Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nadi	Lavusa Rd	Lavusa Bridge	Debris on Deck	7/2/17=7.30 am	Closed to all traffic	Clear Silt & debris once Water recedes	7-Feb-17		
Nadi	Togo Rd	Togo Cross Culvert	Washout/Scour	7/2/17=7.30 am	Closed to all traffic	Backfill Washout	TBA		



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Nadi	Wailoko Rd	Wailoko Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic			07/02/17 3pm	Water receded. debris cleared
Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding	7/2/17=7.30 am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nadi	Naseveia Rd	Crossing	Flooding	7/2/17=2.30 pm	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nadi	Nawaicoba Rd		Flooding	7/2/17=2.30 pm	Closed to light vehicles	Awaiting Water Level to Recede	TBA		
Sigatoka	Kavanagasa Rd	Raiwaqa crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Nabaka Rd	Nabaka Crossing	Underwater by 1 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Uluisila Rd	Uluisila crossing	Underwater by 0.5 M	07.02.2017 7 am	Caution - level raising			07/02/2017 3pm	Water level fully receded
Sigatoka	Nadroumai Rd	Nadroumai crossing	Underwater by 0.5 M	07.02.2017 7 am	Caution - level raising			07/02/2017 3pm	Water level fully receded



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

Sigatoka	Nasau Rd	Lawai crossing	Underwater by 0.5 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Dreke Rd	Near the Village	Landslide	07.02.2017 10.30 am	Open to 4x4 only	Awaiting Water Level to Recede	TBA		
Sigatoka	Tilivalevu Rd	Qwali Flat	Underwater by 0.5 M	07.02.2017 10.30 am	Open to 4x4 only	Awaiting Water Level to Recede	TBA		
Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Valley Rd	Draiba crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

NORTHERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Labasa	Nakorotari Road	Navakuru Crossing	Approach washout	1200 07/2/17	Closed	Reinstate Washout once water recedes	Unknown		Pending



Situation Report TD09F- 03
8am- Wednesday 8 February 2017

EASTERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Nabukelevu-i-ra	CH 4.5km	Landslip	6pm 07/02/17	One lane open	Clearing in progress	8/2/2017		Pending

-END-

For more information please contact the Communications Team at communications@fijiroads.org or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.