



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Re: **TD09F Situation Report No. 4 as at 1200 Hours – Wednesday 8 February 2017**

This situation report is to advise of the status of FRA's assets due to the effects of TD09F.

- Queens Road at Waimalika, Nadi is open only to Heavy Vehicles and 4WD
- Queens Road at Nadi Back Road along Tata's Restaurant to Pacific Energy is closed to all light vehicles
- Kings Road between Ba and Tavua at the Natawa Bridge is closed to traffic.
- Kings Road at Tavua Town is closed to traffic as Tavua Bridge is under water.
- Kings Road from the Korotale Junction to the new Rakiraki Bridge is closed to traffic.
- Next high tide is at 4:26pm this afternoon and tomorrow morning at 5:00am.
- Water level continues to rise in these affected areas and the public are advised to restrict travel in affected areas.
- Some roads in the urban and low-lying areas are still in danger of flooding as rainfall continues in some parts of Fiji.
- Please remain vigilant, tune into the local radio and listen to the advice of emergency services.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

CENTRAL DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	1200 06/2/17	Closed	Monitor water levels	Unknown		
Levuka	Ovalau Circular Rd	Rukuruku Crossing	Water receded	1000 06/2/17	Closed to heavy vehicles	Reinstate washout	Unknown		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

WESTERN DIVISION

Road ID	Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Barotu Cr Road	Rakiraki	Barotu Cr Road	Nailawa Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Burenitu	Rakiraki	Burenitu Road	Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Narara Road	Rakiraki	Narara Road	4 Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Korotale Road	Rakiraki	Korotale Road	Naqoro Flat	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Kings Road	Rakiraki	Kings Rd	Nadovi Flat	Flooding	8/2/17-11am	Closed to all traffic	Water Level is Rising	TBA		
Vatukacevaceva	Rakiraki	Vatukacevaceva Rd	Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Lau Road	Rakiraki	Lau Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nausori Road	Rakiraki	Nausori Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Ganilau Rd	Rakiraki	Ganilau Rd	Crossing	Flooding, washout	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nasau Rd	Rakiraki	Nasau Road	Savusavu	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

			Crossing							
Navuniyau munu Road	Rakiraki	Nanuniy aumunu Rd	Nanuniy aumunu Crossing	Approach Washout	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nailuva Road	Rakiraki	Nailuva Road	Burelev u Crossing	Flooding	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Katudrau Road	Rakiraki	Katudra u Road	Katudra u Crossing	Flooding	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Waimari Road	Rakiraki	Waimari Road	Qalau Flat	Fooding	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
FSC road	Rakiraki	FSC Road	Towards The Mill	Flooding	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki Access Road	Rakiraki	Rakiraki Access	Towards the Penang Mill From Rakiraki Village	Flood	8/2/17- 11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nasomo	Tavua	Nasomo	CH300	Culvert Washout	8/2/17 - 11.00am	Rd Closed	Re-Install the culvert and backfill			



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Yaladro	Tavua	Yaladro	CH0- Ch4600	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Nabuna Village Rd	Tavua	Nabuna Village Rd	CH0- Ch700	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Rukuruku	Tavua	Rukuruku	CH2500 -Ch3000	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Lakalaka	Tavua	Lakalaka	CH800	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Dramasi	Tavua	Dramasi	CH200	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Nadelei	Tavua	Nadelei	CH1400	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Naseyani	Tavua	Naseyani	Ch2400	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		
Mataniwai Rd		Mataniwai Rd	CH1300	Underwater	8/2/17 - 11.00am	Closed to all traffic	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Navala Road	Ba	Navala Road	Navala Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Varadoli Cemetry Road	Ba	Varadoli Cemetry Road	Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Varadoli Road	Ba	Varadoli Road	Crossing	Crossing under water	08.02.2017=11am	Open to all traffic	To be Advised When Water Recedes	TBA		
Koroboya Road	Ba	Koroboya Road	Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Vutuni Road	Ba	Vutuni Road	3rd Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		

Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Marinitawa Road	Ba	Marinitawa Road	1st Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Toge Road	Ba	Toge Road	1st Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Babrihan Road	Ba	Babrihan Road	1st Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Elevuka Road	Ba	Elevuka Road	1st Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Namosau Road	Ba	Namosau Road	Bridge	Bridge under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Koula Road	Ba	Koula Road	Bridge	Bridge under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Navula Road	Lautoka	Navula Road	Navula Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Buabua Road	Lautoka	Buabua Road	Buabua Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Vakabuli Paipai Road	Lautoka	Vakabuli Paipai Road	Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Drasa Dam Road	Lautoka	Drasa Dam Road	Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Vaivai Road	Lautoka	Vaivai Road	Vaivai Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Saru Back Road	Lautoka	Saru Back Road	Saru Crossing	Under water	8/2/17=8.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Abaca Road	Lautoka	Abaca Road		Under water	7/2/17=11.25pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Tomuka Road	Lautoka	Tomuka Road		Under water	8/2/17=11.25pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
B.S.Charan	Lautoka	B.S.Charan		Reinstated	8/2/17=7.30am	Open to all traffic	Culvert reinstated	TBA	7/2/17=4.00pm	



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Vuda Back Road	Lautoka	Vuda Back Road		Road under water	8/2/17=9.20am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Vakabuli Paipai Road	Lautoka	Vakabuli Paipai Road	2nd Crossing	Bridge approach wash out	7/2/17=11.30pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Buabua Road	Lautoka	Buabua Road	Buabua Flat	Road Flooded	8/2/17=8.30am	Only open to big trucks & 4 wheel drive	To be Advised When Water Recedes	TBA		
Field 40 Tramline	Lautoka	Field 40 Tramline	Field 40 Tamline Flat	Under water	8/2/17=8.55am	Closed To All Traffic	To be Advised When Water Recedes	TBA		

Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Saru Road	Lautoka	Saru Road	Saru Bridge	Under water	8/2/17=9.00am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
J.P.Bally Rd	Lautoka	J.P.Bally Rd	Navutu	Under water	8/2/17=11.00pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Natabua Seaside Rd	Lautoka	Natabua Seaside Rd	Natabua	Under water	8/2/17=11.00pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Queens Rd- Navutu	Lautoka	Queens Rd - Navutu	Navutu Flat	Under water	8/2/17=11.00pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Nadi Back Rd	Nadi	Nadi Back Rd	Along Tata'S Resturant to Pacific Energy	Flooding	6/2/17=3.00pm	Open to 4x4 and heavy vehicles only. Drive with Caution			Water level receded	



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Queens Road	Nadi	Queens Road	Waimalika	Flooding	8/02/2017 8am	Open to 4x4 and heavy vehicles only. Drive with Caution				
Solovi Rd	Nadi	Solovi Rd	Solovi Rd Crossing 1 & 2	Flooding	7/2/17=7.3 0am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Mate Rd	Nadi	Mate Rd	Mate Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Arolevu Rd	Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Chunilal Rd	Nadi	Chunilal Rd	Chunilal Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Savalau Rd	Nadi	Savalau Rd	Savalau Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Lavusa Rd	Nadi	Lavusa Rd	Lavusa Bridge	Debris on Deck	7/2/17=7.3 0am	Closed to all traffic	Clear Silt & debris once Water recedes	7-Feb-17		
Togo Rd	Nadi	Togo Rd	Togo Cross Culvert	Washout/ Scour	7/2/17=7.3 0am	Closed to all traffic	Backfill Washout	TBA		



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Wailoko Rd	Nadi	Wailoko Rd	Wailoko Crossing	Flooding	7/2/17=7.30am	Closed to all traffic			07/02/17 3pm	Water receded. debris cleared
Namulomulo Rd	Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding	7/2/17=7.30am	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nasesevia Rd	Nadi	Nasesevia Rd	Crossing	Flooding	7/2/17=2.30pm	Closed to all traffic	Clear Silt & debris once Water recedes	TBA		
Nawaicoba Rd	Nadi	Nawaicoba Rd		Flooding	7/2/17=2.30pm	Closed to light vehicles	Awaiting Water Level to Recede	TBA		
Kavanagasau	Sigatoka	Kavanagasau Rd	Raiwaqa crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Bukuya	Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Nabaka	Sigatoka	Nabaka Rd	Nabaka Crossing	Underwater by 1 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Uluisila	Sigatoka	Uluisila Rd	Uluisila crossing	Underwater by 0.5 M	07.02.2017 7 am	Caution - level level raising			07/02/2017 3pm	Water level fully receded
Nadroumai	Sigatoka	Nadroumai Rd	Nadroumai crossing	Underwater by 0.5 M	07.02.2017 7 am	Caution - level level raising			07/02/2017 3pm	Water level fully receded



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

Nasau	Sigatoka	Nasau Rd	Lawai crossing	Underwater by 0.5 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Dreke	Sigatoka	Dreke Rd	Near the Village	Landslide	07.02.2017 10.30 am	Open to 4x4 only	Awaiting Water Level to Recede	TBA		
Tilivalevu Rd	Sigatoka	Tilivalevu Rd	Qwali Flat	Underwater by 0.5 M	07.02.2017 10.30 am	Open to 4x4 only	Awaiting Water Level to Recede	TBA		
Wauosi	Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Valley	Sigatoka	Valley Rd	Draiba crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		

NORTHERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Labasa	Nakorotari Road	Navakuru Crossing	Approach washout	1200 07/2/17	Closed	Reinstate Washout once water recedes	Unknown		Pending



Situation Report TD09F- 04
12pm- Wednesday 8 February 2017

EASTERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Nabukelevu-i-ra	CH 4.5km	Landslip	6pm 07/02/17	One lane open	Clearing in progress	8/2/2017		Pending
Vunisea	Nabukelevu-i-ra	CH 29km	Crossing approach washout	1:35pm 08/02/17	Closed				Pending

-END-

For more information please contact the Communications Team at communications@fijiroads.org or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.