



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

**Re: TD09F Situation Report No. 7 as at 1200 Hours – Thursday 9 February 2017**

This situation report is to advise of the status of FRA's assets due to the effects of TD09F.

- Queens Road is open
- Kings Road is open
- A number of roads still remain closed and impassable, especially in the Western Division. Please take extra caution.
- Members of the public travelling on the Bau Tikina Road are urged to exercise extreme caution. This follows the recent road slips that has necessitated additional barricades and one way restrictions on sections of this road.
- There are still a number of Irish crossings flooded at the moment. FRA contractors will carry out reinstatement work as the water level recedes.
- Increased number of potholes on the road network and the FRA contractors have commenced remedial works. Motorists are advised to drive with caution during this time.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.

Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

### WESTERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractor's Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Rakiraki	Korotale Road	Naqoro Flat	Flooding	8/2/17-11am	Open to all vehicles			09/02/17 10am	Water level receded. Debris cleared
Rakiraki	Vatukacevaceva Rd	Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Lau Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nausori Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Ganilau Rd	Crossing	Flooding, washout	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Rakiraki	Nasau Road	Savusavu Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nanuniyaumunu Rd	Nanuniyaumunu Crossing	Approach Wasout	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nailuva Road	Burelevu Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Katudrau Road	Katudrau Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Nasomo	CH300	Culvert Washout	8/2/17 - 11.00am	Closed to all traffic	Re-Install culvert and backfill when water recedes	TBA		
Tavua	Yaladro	CH0-Ch4600	Underwater	8/2/17 - 11.00am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Nabuna Village Rd	CH0-Ch700	Underwater	8/2/17 - 11.00am	Open to 4x4 vehicles only	Water is receding	09/02/17 5pm		

Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Tavua	Rukuruku	CH2500- Ch3000	Underwater	8/2/17 - 11.00am	Open to 4x4 vehicles only	Water is receding	09/02/17 5pm		
Tavua	Lakalaka	CH800	Underwater	8/2/17 - 11.00am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Dramasi	CH200	Underwater	8/2/17 - 11.00am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Nadelei	CH1400	Underwater	8/2/17 - 11.00am	Open to all traffic			09/02/17 11pm	Water Receded
Tavua	Naseyani	Ch2400	Underwater	8/2/17 - 11.00am	Work in progress. Closed to all vehicles	Backfill approach and clear debris	09/02/17 3pm		
Tavua	Mataniwai Rd	CH1300	Underwater	8/2/17 - 11.00am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Qalela Rd	CH5500	Culvert Approach washout	9/2/17 - 11.00am	Closed to all traffic	Reinstate Culvert & Backfill	TBA		
Tavua	Matacawa Rd	CH1500	Approach washout	9/2/17 - 11.00am	Closed to all traffic	Backfill Approach	TBA		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Ba	Navala Road	Navala Crossing	Crossing under water	08.02.2017 =11am	<b>Closed to all traffic</b>	To be Advised When Water Recedes	TBA		
Ba	Varadoli Cemetry Road	Crossing	Crossing under water	08.02.2017 =11am	<b>Closed to all traffic</b>	To be Advised When Water Recedes	TBA		
Ba	Varadoli Road	Crossing	Crossing under water	08.02.2017 =11am	<b>Open to all traffic</b>			09/02/17 11am	Water receded
Ba	Vutuni Road	3rd Crossing	Crossing under water	08.02.2017 =11am	<b>Closed to all traffic</b>	To be Advised When Water Recedes	TBA		
Ba	Marinitawa Road	1st Crossing	Crossing under water	08.02.2017 =11am	<b>Closed to all traffic</b>	To be Advised When Water Recedes	TBA		
Ba	Toge Road	1st Crossing	Crossing under water	08.02.2017 =11am	<b>Closed to all traffic</b>	To be Advised When Water Recedes	TBA		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Ba	Babriban Road	1st Crossing	Crossing under water	08.02.2017 =11am	Closed to all traffic	backfilling of approach is underway	Temporary access- 09.02.20 17- 3pm Full access 10.02.20 17- 5pm		
Ba	Namosau Road	Bridge	Bridge under water	08.02.2017 =11am	Closed to all traffic	1st stage- clear silt from surface due to slipperines and fallen tree to make lane traffic. 2nd stage- clear debris once 2 lane traffic will be open	Clear silt from surface- 09.02.20 17- 12pm Clear debris 10.02.20 17- 3pm		
Ba	Koula Road	Bridge	Bridge under water	08.02.2017 =11am	Closed to light vehicles	Grading to fill scoured section	10.02.20 17- 10am		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Ba	Koronubu road	road	Carriageway under water	09.02.2017 10am	Closed to light traffic	To be Advised When Water Recedes	TBA		
Ba	koroboya road	Crossing	Approach washed away	09.02.17= 11am	Closed To All Traffic	backfilling of approach is underway	09.02.20 17= 5pm		
Lautoka	Navula Road	Navula Crossing	Under water	8/2/17=8.0 0am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Buabua Road	Buabua Crossing	Under water	8/2/17=8.0 0am	Open to all traffic	Work in progress to backfill approach	TBA		
Lautoka	Vakabuli Paipai Road	Crossing	Under water	8/2/17=8.0 0am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Drasa Dam Road	Crossing	Under water	8/2/17=8.0 0am	Closed To All Traffic	To be Advised When Water Recedes	TBA		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Lautoka	Vaivai Road	Vaivai Crossing	Under water	8/2/17=8.0 0am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Saru Back Road	Saru Crossing	Under water	8/2/17=8.0 0am	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Abaca Road		Under water	7/2/17=11. 25pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Tomuka Road		Under water	8/2/17=11. 25pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Lautoka	Vakabuli Paipai Road	2nd Crossing	Bridge approach wash out	7/2/17=11. 30pm	Closed To All Traffic	To be Advised When Water Recedes	TBA		
Nadi	Solovi Rd	Solovi Rd Crossing 1 & 2	Flooding	7/2/17=7.3 0am	Open to all traffic			09/02/17 10am	Water level receded





Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Nadi	Mate Rd	Mate Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Chunilal Rd	Chunilal Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Savalau Rd	Savalau Crossing	Flooding	7/2/17=7.3 0am	Open to all traffic			09/02/17 10am	Water level receded
Nadi	Lavusa Rd	Lavusa Bridge	Debris on Deck	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Togo Rd	Togo Cross Culvert	Washout/Scour	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Wailoko Rd	Wailoko Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Approach being reinstated today	09/02/17 5pm		
Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding	7/2/17=7.3 0am	Closed to all traffic	Clear Silt & debris once	09/02/17 5pm		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

						Water recedes			
Nadi	Naseveia Rd	Crossing	Flooding	7/2/17=2.3 0pm	Closed to all traffic	Clear Silt & debris once Water recedes	09/02/17 5pm		
Nadi	Nawaicoba Rd		Flooding	7/2/17=2.3 0pm	Open to all traffic			09/02/17 10am	Water level receded
Nadi	Nalovo Rd	Nalovo School Rd Crossing	Flooding, Approach washout	09/02/17 9am	Closed to all traffic	Reinstate approach	TBA		
Sigatoka	Kavanagasau Rd	Raiwaqa crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Nabaka Rd	Nabaka Crossing	Underwater by 1 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Nasau Rd	Lawai crossing	Underwater by 1 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Sigatoka	Dreke Rd	Near the Village	Landslide	07.02.2017 10.30 am	Open to 4x4 van only	Awaiting Water Level to Recede	TBA		
Sigatoka	Tilivalevu Rd	Qwali Flat	Underwater by 1.5 M	07.02.2017 10.30 am	Closed to all traffic	Wait for the water to recede	TBA		
Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Valley Rd	Draiba crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Yalasuna/Waibogi Rd	0.2 Km from the junction	Underwater by 1 M	08.02.2017 9 am	Open to all traffic			09.02.2017 8.30 am	Water receded
Sigatoka	Uluisila Rd	Uluisila Crossing	Underwater by 1 M	08.02.2017 9 am	Open to all traffic			09.02.2017 8.30 am	Water receded
Sigatoka	Nadroumai Rd	Nadroumai Crossing	Underwater by 1 M	08.02.2017 9 am	Open to all traffic			09.02.2017 8.30 am	Water receded
Sigatoka	Malomalo Rd	Malomalo Flat	Underwater by 1 M	08.02.2017 2 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		

Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

Sigatoka	Navisabasaba Rd	0.2 Km from the junction	Underwater by 1 M	08.02.2017 2 pm	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Sigatoka	Ciri Rd	Nalele Flat	Underwater by 1 M	08.02.2017 2 pm	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Sigatoka	Kabisi Rd	Kabisi crossing	Underwater by 1 M	08.02.2017 2 pm	<b>Open to all traffic</b>			09.02.2017 8.30 am	Water receded
Sigatoka	Nasauco Rd	Nasauco	Very muddy	08.02.2017 2 pm	<b>Open to 4x4 vehicles only</b>	Awaiting Water Level to Recede	TBA		

Situation Report TD09F- 07  
 12pm- Thursday 9 February 2017

**CENTRAL DIVISION**

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	1200 06/2/17	Closed	Monitor water levels	Unknown		
Levuka	Ovalau Circular Rd	Rukuruku Crossing	Water receded	1000 06/2/17	Closed to heavy vehicles	Reinstate washout	Unknown		



Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

**NORTHERN DIVISION**

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Time/Date Resolved	How Resolved
Labasa	Nakorotari Road	Navakuru Crossing	Approach Washout	3:00pm 07/02/17	Closed to all traffic	Reinstate Washout once water recedes		
Labasa	Vuniyalayala Road	CH 985	Washout culvert	8:30am 08/02/17	Closed to all traffic	Reinstate Washout once water recedes		
Natua	Drawa Road	Drawa Crossing	Approach Washout	8:00am 09/02/17	Closed to all traffic	Reinstate Washout once water recedes		
Natua	Zailav Road	Zailav Crossing	Underwater	8:00am 09/02/17	Closed to all traffic	Monitor - wait for water to recede		
Labasa	Boca Loop	Culvert 0/1	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		
Labasa	Urata Road	Culvert 0/1	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		
Labasa	Bulileka Road	Bridge 4/2	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		
Labasa	Qawa	Bridge 0/1	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		
Labasa	Naduna	Nakama Crossing	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		
Labasa	Siberia Road	Imly Point	Flooded	8:00am 09/02/17	Closed to all traffic	Wait for flood waters to recede		

Situation Report TD09F- 07  
12pm- Thursday 9 February 2017

### EASTERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Nabukelevu-i-ra	CH 4.5km	Landslip	6pm 07/02/17	Road open	Clearing work completed	8/2/2017	08/02/17	Clearing work completed
	Nabukelevu-i-ra	Chainage 29 Tabuya Box-Culvert Crossing	Approach washed away	1330Hrs 08/02/17	Road Open	Approaches reinstated	08/02/17	08/02/17	Approaches reinstated

**-END-**

For more information please contact the Communications Team at [communications@fijiroads.org](mailto:communications@fijiroads.org) or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.