



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

**Re: TD09F Situation Report No. 12 as at 1100 Hours – Sunday 12 February 2017**

This situation report is to advise of the status of FRA's assets due to the effects of TD09F.

- A number of roads still remain closed and impassable, especially in the Western and Northern Division. Please find alternative routes where possible and take extra caution.
- Members of the public travelling on the Bau Tikina Road are urged to exercise extreme caution. This follows the recent road slips that has necessitated additional barricades and one way restrictions on sections of this road.
- There are still a number of Irish crossings still flooded at the moment. FRA contractors will continue to carry out reinstatement work as the water level recedes.
- Higgins have commenced pothole repair works along Queens and Kings Road. Once this is under control they will move into the CBD areas and residential roads.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

**WESTERN DIVISION**

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Rakiraki	Burenitu Road	Crossing	Flooding	12/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Vatukacevaceva Rd	Crossing	Flooding	12/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Lau Road	Fort Crossing	Flooding	12/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nausori Road	Fort Crossing	Flooding	12/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Naqoro Flat	Rakiraki Town Approach	Flooding	12/2/17-7am	Open to 4 x 4 & heavy vehicles only. water level is rising	Awaiting Water Level to Recede	TBA		
Rakiraki	Korotale Road	Drana Crossing	Flooding	12/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

Rakiraki	Nasau Road	Savusavu Crossing	Flooding	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Rakiraki	Nanuniyau munu Rd	Nanuniyau munu Crossing	Approach Wasout	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Rakiraki	Nailuva Road	Burelevu Crossing	Flooding	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Rakiraki	Katudrau Road	Katudrau Crossing	Flooding	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Rakiraki	Waimari Road	Qalau Flat	Fooding	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	TBA		
Tavua	Nasomo	CH300	Culvert Washout	12/2/17-7am	<b>Closed to all traffic</b>	Re-Install culvert and backfill when water recedes	13/02/17 10am		
Tavua	Lakalaka	CH800	Underwater	12/2/17-7am	<b>Closed to all traffic</b>	Awaiting Water Level to Recede	12/02/17 3pm		
Tavua	Qalela Rd	CH5500	Culvert Approach washout	12/2/17-7am	<b>Closed to all traffic</b>	Reinstate Culvert & Backfill	13/02/17 5pm		
Tavua	Matacawa Rd	CH1500	Approach washout	12/2/17-7am	<b>Closed to all traffic</b>	Backfill Approach	13/02/17 5pm		



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

Ba	Navala Road	Navala Crossing	Crossing under water	12/2/17-7am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Vutuni Road	3rd Crossing	Crossing under water	12/2/17-7am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Marinitawa Road	1st Crossing	Crossing under water	12/2/17-7am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Yaloku Crossing	crossing	Crossing under water	12/2/17-7am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Maururu Rd	road	Road deformation	12/2/17-7am	Open to 4 x 4 vehicles only.	Digout and repair	TBA		
Ba	Koula Rd	Culvert	Road Drop out	12/2/17-7am	Closed to all traffic	Reinstate Culvert & Backfill when the rain stops	TBA		
Lautoka		Navula Road	Navula Crossing	Road Drop out	12/02/17 =7.15am	Closed to all traffic	To be reinstated when weather permits	TBA	
Lautoka	Vakabuli Indian School		Approach washout	12/02/17 =7.15am	Closed to all traffic	Work in progress	TBA		
Nadi	Mate Rd	Mate Crossing	Flooding	7/2/17=7.30am	Closed to all traffic	To be Advised When Water Recedes	TBA		



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.30am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Nadi	Savalau Rd	Savalau Crossing No.2	Flooding	11/02/17 11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Nadi	Togo Rd	Togo Cross Culvert	Washout/Scour	11/02/17 11.30am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding, approach washout	7/2/17=7.30am	Closed to all traffic	Work in progress	12/02/17 5pm		
Nadi	Rt Meli Rd	Crossing	Decking, pavement washout	10/02/2017 7.30am	Closed to all traffic	Approach being reinstated today	12/02/2017 5pm		
Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	12/02/17 =7.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Dreke Rd	Near the Village	Landslide	12/02/17 =7.30am	Open to 4x4 vehicles only	Clear landslide	TBA		
Sigatoka	Tilivalevu Rd	Qwali Flat	Underwater by 1.5 M	12/02/17 =7.30am	Open to all traffic			12/02/17 7am	Water level is receding
Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	12/02/17 =7.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Ciri Rd	Nalele Flat	Underwater by 1 M	12/02/17 =7.30am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Nasaucoko Rd	Nasaucoko	Very muddy	12/02/17 =7.30am	Open to 4x4 vehicles only	Clear mud when rain stops	TBA		



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

**CENTRAL DIVISION**

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	1200 06/2/17	Closed	Monitor water levels	Unknown		
Levuka	Ovalau Circular Rd	Rukuruku Crossing	Water receded	1000 06/2/17	Closed to heavy vehicles	Reinstate washout	Unknown		

**EASTERN DIVISION**

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Tavuki Road	Ch 9km Just before Baidamudamu Village	Culvert approach Washout	1200hrs 10/02/17	Road Closed	Attend and fix approach and washout	2/16/2017	0900hrs 16/02/17	



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

**NORTHERN DIVISION**

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Labasa	Nakorotari Road	Navakuru Crossing	Approach Washout	3:00pm 07/02/17	Closed to all traffic	Reinstate Washout once water recedes. Water receded. Midday update 11/02/17 - approach washout again. Reinstate once water recedes	TBC		Pending
Labasa	Vuniyalayala Road	CH 985	Washout culvert	8:30am 08/02/17	Open to all traffic	Reinstate Washout once water recedes. Water receded		4:00pm 09/02/17	Complete
Natua	Drawa Road	Drawa Crossing	Approach Washout	8:00am 09/02/17	Closed to all traffic	Reinstate Washout once water recedes	TBA		Pending
Natua	Zailav Road	Zailav Crossing	Underwater	8:00am 09/02/17	Closed to all traffic	Still underwater at 4:00pm 10/02/17. Crossing still under water midday update 11/02/17	TBA		Pending
Labasa	Boca Loop	Culvert 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water Receded		12:00pm 09/02/17	Complete
Labasa	Urata Road	Culvert 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		4:00pm 09/02/17	Complete



Situation Report TD09F- 12  
11am- Sunday 12 February 2017

Labasa	Bulileka Road	Bridge 4/2	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water Receded		12:00pm 09/02/17	Complete
Labasa	Qawa	Bridge 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		4:00pm 09/02/17	Complete
Labasa	Naduna	Nakama Crossing	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		4:00pm 09/02/17	Complete
Labasa	Siberia Road	Imly Point	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		4:00pm 09/02/17	Complete
Natua	Movo	50m	Collapse culvert	12:00pm 09/02/17	Closed to all traffic	Wait for flood waters to recede. Repair culvert	TBA		Pending
Natua	Kawakawave si	12.212km	Crossing underwater	12:00pm 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded.	TBA		Complete
Natua	Lalakoro	6.112km	Crossing underwater	12:00pm 09/02/17	Closed to all traffic	Wait for flood waters to recede. Water receded. Water has risen again at 4:00pm 10/02/17 update. Closed to traffic. Currently still underwater midday update 11/02/17	TBA		Pending
Natua	Buavou	492m	Crossing underwater	12:00pm 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded.	TBA		Complete
Labasa	Vuniyalayala Road	Vuniyalayala Low Level Bridge Crossing	Concrete Bridge Deck has sustained significant damage.	4:00pm 09/02/17	Closed to all traffic	Inspection, design and repairs required to concrete bridge deck. Bridge closed indefinitely. NOTE: This is a loop road and the road is still open and accessible to all	TBA		Pending





Situation Report TD09F- 12  
11am- Sunday 12 February 2017

						vehicles, but the bridge is closed to all traffic.			
Labasa	Bulileka Rd	Dreketilailai Crossing	Approach Washout	8:30am 10/02/17	Closed to all traffic	Reinstate washout	4:00pm 10/02/17		Pending
Labasa	Loveline Road	Loveline Bridge	Approach Washout	8:30am 10/02/17	Closed to all traffic	Reinstate washout	4:00pm 10/02/17		Pending
Labasa	Wainikoro Road	CH 55km - 63km	Depressed red clay sections of road causing driving hazards	12:00pm 11/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	5:00pm 11/02/17		Pending
Natua	Nabouwalu Road	Nabouwalu - Daria Road	Saturated pavement causing boggy sections	4:00pm 11/02/17	Open to 4WD. Drive with care	Pavement repairs once rain ceases	TBA		Pending

**-END-**

For more information please contact the Communications Team at [communications@fijiroads.org](mailto:communications@fijiroads.org) or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.