



Situation Report TD09F
8am- Saturday 11 February 2017

Re: TD09F Situation Report No. 11 as at 0800 Hours – Saturday 11 February 2017

This situation report is to advise of the status of FRA's assets due to the effects of TD09F.

- A number of roads still remain closed and impassable, especially in the Western Division. Please take extra caution.
- Members of the public travelling on the Bau Tikina Road are urged to exercise extreme caution. This follows the recent road slips that has necessitated additional barricades and one way restrictions on sections of this road.
- There are still a number of Irish crossings still flooded at the moment. FRA contractors will continue to carry out reinstatement work as the water level recedes.
- Higgins have commenced pothole repair works along Queens & Kings Road. Once this is under control they will move into the CBD areas and residential roads.
- Increased number of potholes on the road network. Remedial works have commenced however the approaching TD10F and TD11F will impact work progress causing delays.

Members of the public can contact FRA on 5720 if they have queries regarding the affected roads and crossings.



Situation Report TD09F- 11
8am- Saturday 11 February 2017

WESTERN DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Rakiraki	Burenitu Road	Crossing	Flooding	11/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Korotale Road	Naqoro Flat	Flooding	11/2/17-7am	Open to Traffic, Drive with Caution as water level is rising	Awaiting Water Level to Recede	TBA		
Rakiraki	Vatukacevac eva Rd	Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Lau Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nausori Road	Fort Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nasau Road	Savusavu Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nanuniyaumu Rd	Nanuniyaumunu Crossing	Approach Wasout	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Nailuva Road	Burelevu Crossing	Flooding	8/2/17-11am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Rakiraki	Katudrau Road	Katudrau Crossing	Flooding	11/2/17-7am	Open to heavy vehicles only. Water level rising	Awaiting Water Level to Recede	TBA		



Situation Report TD09F- 11
8am- Saturday 11 February 2017

Rakiraki	Waimari Road	Qalau Flat	Fooding	11/2/17-7am	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Tavua	Nasomo	CH300	Culvert Washout	8/2/17 -11.00am	Closed to all traffic	Re-Install culvert and backfill when water recedes	13/02/17 10am		
Tavua	Lakalaka	CH800	Underwater	8/2/17 -11.00am	Closed to all traffic	Awaiting Water Level to Recede	11/02/17 3pm		
Tavua	Dramasi	CH200	Underwater	8/2/17 -11.00am	Open to all traffic			11/02/17 7am	Water receded
Tavua	Qalela Rd	CH5500	Culvert Approach washout	9/2/17 -11.00am	Closed to all traffic	Reinstate Culvert & Backfill	12/02/17 5pm		
Tavua	Matacawa Rd	CH1500	Approach washout	9/2/17 -11.00am	Closed to all traffic	Backfill Approach	12/02/17 5pm		
Ba	Navala Road	Navala Crossing	Crossing under water	08.02.2017=11am	Open to 4 x 4 vehicles only. No damages But water level still high.	To be Advised When Water Recedes	TBA		
Ba	Vutuni Road	3rd Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Marinitawa Road	1st Crossing	Crossing under water	08.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Yaloku Crossing	crossing	Crossing under water	10.02.2017=11am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Ba	Maururu Rd	road	Road deformation	11.02.2017=11am	Open to 4 x 4 vehicles only.	Digout and repair	TBA		
Ba	Toge Road	1st Crossing	Crossing under water	08.02.2017=11am	Open to all traffic			10/02/17 5pm	Water receded, Debris cleared



Situation Report TD09F- 11
8am- Saturday 11 February 2017

Lautoka	Navula Road	Navula Crossing	Road Drop out	10/02/17=7.15am	Closed to all traffic	Work in progress	TBA		
Lautoka	Vakabuli Indian School		Approach washout	10/02/17=7.15am	Closed to all traffic	Work in progress	TBA		
Nadi	Arolevu Rd	Arolevu Crossing	Flooding	7/2/17=7.30am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Nadi	Chunilal Rd	Chunilal Crossing	Flooding	7/2/17=7.30am	Closed to all traffic	To be Advised When Water Recedes	TBA		
Nadi	Wailoko Rd	Wailoko Crossing	Flooding, pavement washout	7/2/17=7.30am	Open to all traffic	Approach being reinstated today		10/02/17 5pm	Backfill with metals and compact
Nadi	Namulomulo Rd	Namulomulo Crossing	Flooding, approach washout	7/2/17=7.30am	Drive with caution. Work in progress	Approach being reinstated today		11/02/17 5pm	
Nadi	Rt Meli Rd	Crossing	Decking, pavement washout	10-Feb-17	Closed to all traffic	Approach being reinstated tomorrow		11/02/2017 5pm	
Nadi	Lomawai Rd	Near Namata	Flooding, culvert washout	10/02/2017 3pm	Drive with caution. Work in progress	Work in progress		11/02/17 5pm	
Sigatoka	Bukuya Rd	Nasivikoso crossing	Underwater by 1 M	06.02.2017 3.30pm	Closed to all traffic	Awaiting Water Level to Recede		TBA	
Sigatoka	Nabaka Rd	Nabaka Crossing	Underwater by 1 M	07.02.2017 7 am	Closed to all traffic	Awaiting Water Level to Recede		TBA	
Sigatoka	Dreke Rd	Near the Village	Landslide	07.02.2017 10.30 am	Open to 4x4 vehicles only	Clear landslide		TBA	
Sigatoka	Tilivalevu Rd	Qwali Flat	Underwater by 1.5 M	07.02.2017 10.30 am	Closed to all traffic	Wait for the water to recide		TBA	
Sigatoka	Wauosi rd	Wauosi crossing	Underwater by 0.5 M	07.02.2017 1 pm	Closed to all traffic	Awaiting Water Level to Recede		TBA	
Sigatoka	Ciri Rd	Nalele Flat	Underwater by 1 M	08.02.2017 2 pm	Closed to all traffic	Awaiting Water Level to Recede		TBA	



Situation Report TD09F- 11
8am- Saturday 11 February 2017

Sigatoka	Nasauco Rd	Nasauco	Very muddy	08.02.2017 2 pm	Open to 4x4 vehicles only	Clear mud when rain stops	TBA		
Sigatoka	Kavanagasa Rd	Raiwaqa Crossing	Underwater by 0.5 M and Strong current & Still Rising	10.02.2017 2.30 pm	Closed to all traffic	Awaiting Water Level to Recede	TBA		
Sigatoka	Kavanagasa Rd	Box Culvert at 16.285 Km	Underwater by 0.2 M and still rising	10.02.2017 2.30 pm	Open to all traffic			11/02/17 7am	Water receded

CENTRAL DIVISION

Depot	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Korovou	Colata Cocoa Rd	Colata Crossing	Flooded	1200 06/2/17	Closed	Monitor water levels	Unknown		
Levuka	Ovalau Circular Rd	Rukuruku Crossing	Water receded	1000 06/2/17	Closed to heavy vehicles	Reinstate washout	Unknown		

Situation Report TD09F- 11
8am- Saturday 11 February 2017

NORTHERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Labasa	Nakorotari Road	Navakuru Crossing	Approach Washout	3:00pm 07/02/17	Open to all traffic	Reinstate Washout once water recedes. Water receded		4:00pm 09/02/17	Complete
Labasa	Vuniyalayala Road	CH 985	Washout culvert	8:30am 08/02/17	Open to all traffic	Reinstate Washout once water recedes. Water receded		4:00pm 09/02/17	Complete
Natua	Drawa Road	Drawa Crossing	Approach Washout	8:00am 09/02/17	Closed to all traffic	Reinstate Washout once water recedes	TBA		Pending
Natua	Zailav Road	Zailav Crossing	Underwater	8:00am 09/02/17	Closed to all traffic	Monitor - wait for water to recede	12:00pm 10/02/17		Pending
Labasa	Boca Loop	Culvert 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water Receded		12:00pm 09/02/17	Complete
Labasa	Urata Road	Culvert 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		4:00pm 09/02/17	Complete
Labasa	Bulileka Road	Bridge 4/2	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water Receded		12:00pm 09/02/17	Complete



Situation Report TD09F- 11
8am- Saturday 11 February 2017

Labasa	Qawa	Bridge 0/1	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded	4:00pm 09/02/17	Complete
Labasa	Naduna	Nakama Crossing	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded	4:00pm 09/02/17	Complete
Labasa	Siberia Road	Imly Point	Flooded	8:00am 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded		Complete
Natua	Movo	50m	Collapse culvert	12:00pm 09/02/17	Closed to all traffic	Wait for flood waters to recede. Repair culvert	TBA	Pending
Natua	Kawakawave si	12.212km	Crossing underwater	12:00pm 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded.	TBA	Complete
Natua	Lalakoro	6.112km	Crossing underwater	12:00pm 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded.	TBA	Complete
Natua	Buavou	492m	Crossing underwater	12:00pm 09/02/17	Open to all traffic	Wait for flood waters to recede. Water receded.	TBA	Complete
Labasa	Vuniyalayala Road	Vuniyalayala Low Level Bridge Crossing	Concrete Bridge Deck has sustained significant damage.	4:00pm 09/02/17	Closed to all traffic	Inspection, design and repairs required to concrete bridge deck. Bridge closed NOTE: This is a loop road and the road is still open and accessible to all vehicles, but the bridge is closed to all traffic.	TBA	Pending
Labasa	Bulileka Rd	Dreketilailai Crossing	Approach Washout	8:30am 10/02/17	Closed to all traffic	Reinstate washout	4:00pm 10/02/17	Pending
Labasa	Lovlove Road	Lovlove Bridge	Approach Washout	8:30am 10/02/17	Closed to all traffic	Reinstate washout	4:00pm 10/02/17	Pending



Situation Report TD09F- 11
8am- Saturday 11 February 2017

EASTERN DIVISION

Depot Area	Road Name	Location Description	Status of Damage	Time/Date Reported	Advice to Motorists	FRA Contractors Action that Will be Taken	Expected Road Opening Date	Time/Date Resolved	How Resolved
Vunisea	Tavuki Road	Ch 9km Just before Baidamudamu Village	Culvert approach Washout	1200hrs 10/02/17	Road Closed	Attend and fix approach and washout	2/16/2017	0900hrs 16/02/17	

-END-

For more information please contact the Communications Team at communications@fijiroads.org or Onarina Umu on +679 9991969 and Zafiya Shamim on +679 9275960.